

Assembly Bill No. 1164

Passed the Assembly September 8, 1999

Chief Clerk of the Assembly

Passed the Senate September 3, 1999

Secretary of the Senate

This bill was received by the Governor this _____ day
of _____, 1999, at _____ o'clock ____M.

Private Secretary of the Governor

└

CHAPTER _____

An act to amend Section 41960.2 of the Health and Safety Code, relating to air pollution.

LEGISLATIVE COUNSEL'S DIGEST

AB 1164, Aanestad. Gasoline vapor recovery control systems.

Existing law requires the State Air Resources Board to identify equipment defects in systems for the control of gasoline vapors resulting from motor vehicle fueling operations, as specified.

This bill would require the executive officer of the state board to identify and list those defects. The bill would also require the executive officer to review that list at a public workshop on or before January 1, 2001, and at least once every 3 years thereafter, to determine whether the list requires updating, as provided. The bill would authorize the executive officer to initiate a public review of the list upon a written request that demonstrates the need for the review, as specified.

The people of the State of California do enact as follows:

SECTION 1. Section 41960.2 of the Health and Safety Code is amended to read:

41960.2. (a) All installed systems for the control of gasoline vapors resulting from motor vehicle fueling operations shall be maintained in good working order in accordance with the manufacturer's specifications of the system certified pursuant to Section 41954.

(b) Whenever a gasoline vapor recovery control system is repaired or rebuilt by someone other than the original manufacturer or its authorized representative, the person shall permanently affix a plate to the vapor recovery control system that identifies the repairer or rebuilder and specifies that only certified equipment was used. In addition, a rebuilder of a vapor control system shall remove any identification of the original



manufacturer if the removal does not affect the continued safety or performance of the vapor control system.

(c) (1) The executive officer of the state board shall identify and list equipment defects in systems for the control of gasoline vapors resulting from motor vehicle fueling operations that substantially impair the effectiveness of the systems in reducing air contaminants. The defects shall be identified and listed for each certified system and shall be specified in the applicable certification documents for each system.

(2) On or before January 1, 2001, and at least once every three years thereafter, the list required to be prepared pursuant to paragraph (1) shall be reviewed by the executive officer at a public workshop to determine whether the list requires an update to reflect changes in equipment technology or performance.

(3) Notwithstanding the timeframes for the executive officer's review of the list, as specified in paragraph (2), the executive officer may initiate a public review of the list upon a written request that demonstrates, to the satisfaction of the executive officer, the need for such a review. If the executive officer determines that an update is required, the update shall be completed no later than 12 months after the date of the determination.

(d) When a district determines that a component contains a defect specified pursuant to subdivision (c), the district shall mark the component "Out of Order." No person shall use or permit the use of the component until the component has been repaired, replaced, or adjusted, as necessary, and the district has reinspected the component or has authorized use of the component pending reinspection.

(e) Where a district determines that a component is not in good working order but does not contain a defect specified pursuant to subdivision (c), the district shall provide the operator with a notice specifying the basis on which the component is not in good working order. If, within seven days, the operator provides the district with adequate evidence that the component is in good



working order, the operator shall not be subject to liability under this division.



Approved _____, 1999

Governor

